

Fig. 1




Fig. 2




Fig. 3




Fig. 4

4/14

Fig. 5





Fig. 6

 $B = 50; \delta = 0.05; S_p = 0.5$ 

5/14

Fig. 7





Fig. 8






Fig. 9

7/14

Fig. 10

$$B = 50; \delta = 0.1; h_p = 1.25; S_p = 0.13$$





Fig. 11

$$B = 50; \delta = 0.1; h_p = 1.25; S_p = 0.13$$



8/14

FIG. 12(a)





FIG. 12(b)

9/14

FIG. 12(c)





FIG. 12(d)




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17